



Figure 8A.

*Thermal imagery showing icing near Tolvana River Crossing*

Figure 8B.

*Oblique photograph of icing site*

Figure 8C.

*Frame photograph of area surrounding icing site*

Figure 8D.

*Strip photograph showing icing site despite considerable uncompensated roll*

Figure 8E.

*Topographic map Livengood B-4*

